DSP Delta / DPA – Released Version Notes

V 1.15. – 20.September.17

- Version Stamped V 1.15.
- Build 23 (Delta 40), 2412 (Delta 80), Build 59 (Delta 100).
- Build 25 (DPA 40), 208 (DPA 80), Build 27 (DPA 100).
- Build 21 (OEM 40), 21 (OEM 80), Build 21 (OEM 100).
- Added Model 40.
- Fixed excessive battery current draw.
- Fixed DHCP requests for Cisco switches.
- Added Network option to switch Auto Negotiation to fixed speeds.

V 1.14. – 14.August.17

- Version Stamped V 1.14.
- Build 2407 (Delta 80), Build 58 (Delta 100).
- Build 160 (DPA 80), Build 26 (DPA 100).
- Fixed Network drop-out and reconnection bug.

V 1.13. – 21.July.17

- Version Stamped V 1.13.
- Build 2384 (Delta 80), Build 54 (Delta 100).
- Build 157 (DPA 80), Build 16 (DPA 100).
- Fixed Delta100/ DPA100 variants limiter thresholds.
- Fixed AutoIp DHCP scanning bug.

V 1.12. – 11.July.17

- Version Stamped V 1.12.
- Build 2382 (Delta 80), Build 20 (Delta 100).
- Reinstated TCP Keep a live message. (Ipad App now happy).

V 1.11. Build 2379 – 07.July.17

- Version Stamped V 1.11.
- Removed WooHoo Always. (Ipad App Not happy).
- Removed TCP Keep a live message. (Ipad App Not happy).

V 1.10. Build 2375 – 05.July.17 (withdrawn)

- Version Stamped V 1.10.
- Recognises Issue 2 PCB with 3.3dB gain lift and compensates.
- Added WooHoo Always.
- Added TCP keep a live message.
- Fixed AES LR channel error.
- Fixed Group membership adding channels with grouping off error.

V 1.09. Build 2358 – 12.May.17

- Version Stamped V 1.09.
- Fixed Configuration change from front panel issue.
- Fixed Protect Led Flash not working in Aux and Input panels.
- Fixed Dante Out mis-clocking error.
- Fixed Network DHCP and Multicast anomolies.
- Added more options to Digital output sources.
- Fixed AES LR channel swap.
- Added Security locking via AudioCore.
- Changed Memory Store / Recall options.
- Changed network timeout back to 200mS. (Was 350mS)
- Fixed cursor on 'Parameter Locked'.
- Fixed wait period on set ID in external interface menu.
- Fixed Remote temperature zero reading.
- Added 'Enter + Quit' on power on to clear Standby mode.

V 1.07. Build 2262 – 17.Mar.17

- Version Stamped V 1.07.
- Fixed Limiter Group Metering bug.
- Fixed Factory Reset code bug and Wake up cycling.
- Add Amp Calibration -20dB option.
- Change IP reset routine for intermittent connections.
- Change possible IP receive buffer overrun.

V 1.05. Build 2226 – 08.Mar.17

- Version Stamped V 1.05.
- Fixed Power supply power-on sequence for alignment routine.

V 1.04. Build 2223 – 03.Mar.17

- Version Stamped V 1.04.
- Fixed Power supply power-on sequence.

V 1.03. Build 2220 – 23.Feb.17

- Version Stamped V 1.03.
- Fixed (Bug129) Clear Settings Limiter Channels 2,3,4.
- Fixed (Bug130) Clear Aux Output Ganging option.
- Fixed (Bug131) Phoenix Code 24BA11 Unit Freeze.

V 1.02. Build 2186 – 17.Feb.17

- Version Stamped V 1.02.
- Updated Grouping commands.
- Add Temperature command 61.

- Fixed Amp output filters copying on Aux channels.
- Fixed some bugs.
- Add More Test Routines.
- Delta Power-on backlite fixed.

Build 2163 – 01.Feb.17

- Version Stamped V 1.01. of 2162.